

NJK-82-345

August 6, 1982

J. Keppler, Regional Director Office of Inspection and Enforcement Region III U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Reference: Quad-Cities Nuclear Power Station

Docket Number 50-254, DPR-29, Unit One

Appendix A. Table 3.1-3

Enclosed please find a supplement to Reportable Occurrence Report Number RO 82-11/01T-1 for Quad-Cities Nuclear Power Station. This occurrence was previously reported to Region III, Office of Inspection and Enforcement by telephone and telecopy on June 5, 1982.

This report is submitted to you in accordance with the requirements of Technical Specification 6.6.B.1.b; operation of the unit with less operable Reactor Protection System instrument subchannels than required by a limiting condition of operation.

Very truly yours,

COMMONWEALTH EDISON COMPANY OUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivianakis

Station Superintendent

NJK: GCT/bb

Enclosures

cc T. J. Rausch N. Chrissotimos INPO Records Center

208200252 820806