USNEC REDUKE POWER COMPANY TLANTA, GEORGIAPOWER BUILDING 422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242 31 DEC 10 A8: 10

WILLIAM O. PARKER, JR. VICE PRESIDENT STEAM PRODUCTION

December 4, 1981

TELEPHONE: AREA 704 373-4083

Mr. J. P. O'Reilly, Director U. S. Nuclear Regulatory Commission Region II 101 Marietta Street, Suite 3163 Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1 Docket No. 50-369



Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/81-174. This report concerns T.S. 3.7.1.2, "At least three independent steam generator auxiliary feedwater pumps and associated flow paths shall be operable ... ". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

Parker /1- legge William O. Parker, Jr.

PBN/jfw Attachment

cc: Director Office of Management and Program Analysis U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Records Center Institute of Nuclear Power Operations 1820 Water Place Atlanta, Georgia 30339

Mr. P. R. Bemis Senior Resident Inspector-NRC McGuire Nuclear Station

B112180349 B11204 PDR ADDCK 0500036