

**BELOIT CORPORATION**  
CASTINGS DIVISION

BELOIT, WISCONSIN, U.S.A. 53511  
AREA CODE 608/365-3311  
INTERNATIONAL TELEX 025-7458  
CABLE ADDRESS: PAPERCHINE



Member Beloit Group

December 3, 1981

United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Attention: L.R. Gleger, Acting Chief  
Technical Inspection Branch

This letter is in response to your "Notice of Violation" in the inspection of 11/12/81. (License No. 48-02412-02)

I.

1. We have discontinued training of our prospective radiographer.
2. Same as above.
3. Compliance will be complete when the licensing division allows the addition of our prospective radiographer.

II.

1. Asked J.L. Lynch to send a copy of the latest 10CFR34 since our copy doesn't have Section "C". We have received the August 1, 1980 copy.
2. Request we be included on the mailing list for new regulations as they are printed. We have received them in the past.
3. We will check dosimeter response to radiation per Section "C" as of this date.

I affirm to the above.

*James W. Miller*  
James W. Miller  
Radiation Safety Officer  
Castings Division  
Beloit Corporation

8112180431 811211  
NMS LIC30  
48-02412-02 PDR

km

DEC 4 1981