

DEC 10 1981

Unity Hospital
ATTN: James Jessup
Administrator
1301 Main Street
Buchanan, MI 49107

License No. 21-18556-01

Gentlemen:

This refers to the routine safety inspection conducted by Ms. E. R. Matson of this office on November 23, 1981, of activities authorized by NRC Byproduct Material License No. 21-18556-01 and to the discussion of our findings with members of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in the enclosed Appendix. A written response, submitted under oath or affirmation, is required.

In addition to the above areas, the inspector examined actions described in your letter dated July 5, 1979, regarding apparent items of noncompliance found during our May 3 and 4, 1979, investigation. One item of noncompliance is a repeat item as noted in the attached Appendix. Include in your response to the recent inspection findings what additional actions you will take to prevent future recurrences of this repeat item of noncompliance. We have no further questions regarding the other apparent items of noncompliance found in 1979.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. J. Sreniawski
D. J. Sreniawski, Chief
Materials Radiation Protection
Section 2



Enclosure: Appendix,
Notice of Violation

cc w/encl:
DMB/Document Control Desk (RIDS)

RIII
Matson
Matson/jp
12/17/81

RIII
Sreniawski
Sreniawski
12/10/81

8112180445 811210
NMS LIC30
21-18556-01 PDR

107
5
11