



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

JAN 20 1994

License: 35-17723-01
Docket: 030-13232

McAlester Regional Health Center
ATTN: Ed Majors, Administrator
One Clark Bass Boulevard
McAlester, Oklahoma 74501

SUBJECT: RESPONSE TO NRC INSPECTION REPORT 030-13232/93-01

Thank you for your letter of December 30, 1993, in response to our letter and Notice of Violation dated December 17, 1993. We have reviewed your reply and find it responsive to the concerns raised in our Notice of Violation. We will review the implementation of your corrective actions during a future inspection to determine that full compliance has been achieved and will be maintained.

Sincerely,

Charles L. Cain

Charles L. Cain, Chief
Nuclear Materials Inspection Section

cc:
Oklahoma Radiation Control Program Director

9401250011 940120
PDR ADOCK 03013232
C PDR

bcc w/copy of licensee letter:

DMB - Original (IE-07)

JLMilhoan

DDChamberlain

LWCamper

MMessier, OC/LFDCB (4503)

WLFisher

CLCain

GLGuerra

NMIS

MIS System

RIV Files (2)

SLMerchant, NMSS/IMAB (6 H3)

240023

RIV:NMIS	C:NMIS <i>ve</i>			
GLGuerra <i>GL</i>	CLCain			
01/19/94	01/19/94			

bcc w/copy of licensee letter:

DMB - Original (IE-07)

JLMilhoan

DDChamberlain

LWCamper

MMessier, OC/LFDCB (4503)

WLFisher

CLCain

GLGuerra

NMIS

MIS System

RIV Files (2)

SLMerchant, NMSS/IMAB (6 H3)

RIV:NMIS	C:NMIS <i>ve</i>			
GLGuerra <i>GLG</i>	CLCain			
01/19/94	01/19/94			




McALESTER REGIONAL HEALTH CENTER

Ed Majors, CHIEF EXECUTIVE OFFICER • One Clark Bass Boulevard • McAlester, Oklahoma 74501 • (918) 426-1800

December 30, 1993

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555



SUBJECT: NRC Inspection Report 030-13232
License 35-17723-01
(Reply to Notice of Violations)

In reference to your letter dated December 17, 1993, we respond to the following items:

ITEM A

- (1) Administration representative had conflicting meetings and was unable to attend the Radiation Safety Committee meetings.
- (2) This violation was corrected in December 1992, when the Assistant Administrator started representing management.
- (3) In the future, an alternate representative of management will attend the Radiation Safety Committee meetings in the absence of the Assistant Administrator.
- (4) December 30, 1992, the Management Representative attended the Radiation Safety Committee Meeting and has continued to be present at these quarterly meetings. A nursing representative was present on December 29, 1993 and will continue to be present at future meetings.

ITEM B

- (1) The geometry test of the dose calibrator was inadvertently overlooked upon installation of this instrument.
- (2) This was corrected and a geometry test was performed on December 7, 1993, and was within specifications.
- (3) All personnel were notified that this procedure must be performed as required by 10CFR35-50(B)(4).


~~940110126~~

94-0388

(4) Compliance with NRC regulations was completed on
December 7, 1993.

Should you have any questions concerning this response,
please contact me at (918) 426-1800.

Sincerely,



Chuck Boss, R.T.(R) CNMT
Director of Diagnostic Imaging
Radiation Safety Officer

cc: Region 4
Arlington, TX

Ed Majors, CEO