

NOTICE OF VIOLATION

Sacramento Municipal Utility District  
Rancho Seco Nuclear Generating Station

Docket No. 50-312  
License No. DPR-54

During an NRC inspection conducted on March 30 through April 20, 1993, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedures for NRC Enforcement Actions," the violation is listed below:

10 CFR 50.9, Completeness and accuracy of information, requires, in part, that information required by statute or by Commission regulations, orders, or license conditions to be maintained by the licensee shall be complete and accurate in all material respects.

Contrary to the above, the licensee determined that records required to be maintained by Commission regulations or license conditions were not complete and accurate in all material respects. Specifically, on at least 28 separate occasions, records made by three Rad-Chem Protection and Decommissioning Technicians and records made by auxiliary operators were identified as being incomplete or inaccurate. These errors were material in that these records evidenced that surveys, and radiation detector verification checks and operator rounds had been made when they had not.

Dated at Walnut Creek, California  
this 4<sup>th</sup> day of January 1994