



# TETON NUCLEAR MEDICINE SERVICE

2001 S. WOODRUFF SUITE 11 • IDAHO FALLS, IDAHO 83404-6370

January 12, 1994

United States Nuclear Regulatory Commission  
Region IV  
ATTN: Document Control Desk  
Washington D.C. 20555

Gentlemen:

SUBJECT: RESPONSE TO NOTICE OF VIOLATION

Reply to Notice of Violation 030-32428/93-01 November 4, 1993

1. Reason for violations were unfamiliarity with 10 CFR 71.5 (a), 49 CFR 173.448 (a) and 49 CFR 177.817 (a).
2. Corrective steps that have been taken:  
Since the day of the inspection, Miguel P. Garcia, dba Teton Nuclear Medicine Service, has not in any manner transported radioactive material out of the plant.
3. Corrective steps that will be taken to avoid further violations:  
Should transportation of radionuclides become necessary, training and familiarization with all appropriate federal regulations and necessary license amendments will be implemented before any such activities begin.
4. As stated above, full compliance has been met since the date of inspection.

Thank You,

Miguel P. Garcia

cc:  
Regional Administrator, Region IV  
Idaho Radiation Control Program Director

9401260187 940112  
PDR ADOCK 03032428  
C PDR

IE07  
110