NRC FORM 591 PART 1 (7-91)

U.S. NUCLEAR REGULATORY COMMISSION

10 CFR 2.201	SAFETY	INSPECTION	Page 1 of
1. LICENSEE Voith Hydro, Inc. Rast Berling Road York, PA 17405		2. REGIONAL OFFICE REGION I U.S. NUCLEAR REGULATOR 475 ALLENDALE ROAD KING OF PRUSSIA PA 194	
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S	5. DATE OF INSPE	CTION
030-15213	37-16280-	03 1/19/54	
LICENSEE: The inspection was an examination of the act Regulatory Commission (NRC) rules and regreprocedures and representative records, interviolities:	ulations and the condition	s of your license. The inspection consisted of	f selective examinations of
questions on those actions at this ti	s you have taken to correct me. ur activities, as described	of the violations identified during the last inspection of NRC representation of NRC re-	
A			ot properly posted to
indicate the presence of a			CFR 20.203(b), (c), (d), (e) or 34.42.
B		of sea	led sources were not
processing		or License Condition Number	
C. Records of Utilizatio	o logs did not a	contain all elements wen	e not properly maintained:
10 CFR 34-27(a)	or License Condition h	Number	
D. Documents were not properly	9402040021	940119 03015213	
E. Reports or notification of	V	PDR	not made in accordance with
10 CFR	or License Condition N	lumber	
F	6.11.1		
DESIGNATED OR Certified by: 25.	IGINAL		
Certified by: 27.	C. P. S. C.		
0300	69		
		Inspector will be taken to correct the violation in the requirements of 10 CFR 2.201. No furth	
SIGNATURE -/LICENSEE/	DATO	SIGNATURE - NRC INSPECTOR	DATE //19/94

NRC FORM 591 Part(1 (7-91)

RETURN GRIDNAL TO REGION I

1E:07 0/