



SACRAMENTO MUNICIPAL UTILITY DISTRICT □ 6201 S Street, Box 15830, Sacramento, California 95813; (916) 452-3211

August 10, 1982

R H ENGELKEN, REGIONAL ADMINISTRATOR  
REGION V OFFICE OF INSPECTION AND ENFORCEMENT  
U S NUCLEAR REGULATORY COMMISSION  
1450 MARIA LANE SUITE 210  
WALNUT CREEK CA 94596

DOCKET NO. 50-312  
OPERATING LICENSE DPR-54  
IE BULLETIN 81-02 SUPPLEMENT: FAILURE OF GATE TYPE VALVES TO  
CLOSE AGAINST DIFFERENTIAL PRESSURE

The Sacramento Municipal Utility District has reviewed IE Bulletin 81-02 Supplement, Failure of Gate Type Valves to Close Against Differential Pressure, dated August 18, 1981. We have determined that there are no valves manufactured by Westinghouse Electro-Mechanical Division (W-EMD) installed, or maintained as spares, at Rancho Seco Nuclear Generating Station, Unit 1. Since no affected valves were identified, no further response to this bulletin supplement is necessary and we will consider this bulletin supplement closed out.

*John J. Mattimoe*

John J. Mattimoe  
Assistant General Manager  
and Chief Engineer

Subscribed and sworn to before me this

17th day of August, 1982.

*Mary Alice Bay*  
Notary Public

MARY ALICE BAY  
NOTARY PUBLIC - CALIFORNIA  
PRINCIPAL OFFICE IN  
SACRAMENTO COUNTY  
My Commission Expires January 29, 1985

1E11