



INSPECTION SERVICE CORPORATION

Box 143 Conshohocken, Pennsylvania 19428
Lab: 216 W. 9th Avenue Phone: (215) 272-1282
82545-31

April 4, 1982
License No. 37-11636-01

UNITED STATES NUCLEAR REGULATORY COMMISSION
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

Attention: Mr. Thomas T. Martin, Director
Division of Engineering and
Technical Inspection

Subject: Inspection No. 81-01
Docket No. 30-6265

Dear Sir:

In reply to your letter dated March 23, 1982, and in conjunction with our letter dated February 12, 1982, I submit to you the following additional information.

1. I have enclosed a copy of the form we intend to use for shipping papers.
2. In my original response to this item I failed to mention that besides acquiring the overpack for our radiographic devices, we have had them lined with high density lead, this has proven to meet the requirements that are provided in our Operating & Emergency Procedure. Also, I am going to submit an ammendment to our license and eliminate the 2 MR/hr reading at the external surfaces of the vehicle, this is not a requirement by the Commission. I thought it had been revised, but on an oversight on my part, we are presently held to it.
3. Mr. Howard Alexander shall be responsible for evaluating our Radiation Safety Program. He shall also be responsible for assuring that future activities are conducted in a manner which will be in full compliance with the requirements of the Commission.

Sincerely,


INSPECTION SERVICE CORPORATION

8205040766 820427
NMS LIC30
37-11636-01 PDR

Howard J. Alexander
Radiation Protection Officer

INSPECTION SERVICE CORPORATION
P.O. Box 143
Conshohocken, Pennsylvania 19428

Phone Numbers: (215) 272-1282
(215) 825-4531

SHIPPING PAPER

Radioactive Material	Special Form N.O.S.
Iridium 192	Special Form
Radioactive Yellow III Label	
Activity in Curies:	