

AUG 19 1982

30-14163

Community Blood Center of  
Greater Kansas City  
ATTN: William Bayer, M.D.  
Director  
4040 Main  
Kansas City, MO 64111

License No. 24-18780-01

Gentlemen:

This refers to the routine safety inspection conducted by Mr. J. R. Madera of this office on August 11, 1982, of activities authorized by NRC Byproduct Material License No. 24-18780-01 and to the discussion of our findings with Mr. L. Parks at the conclusion of the inspection.


The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.


We will gladly discuss any questions you have concerning this inspection.


Sincerely,



D. G. Wiedeman, Chief  
Materials Radiation Protection  
Section 1

cc: Gary E. Tegtmeier, Ph.D.  
Director of Research  
Larry Parks, Lab Supervisor  
DMB/Document Control Desk (RIDS)

RIII   
Madera/jp  
8/18/82

RIII   
Wiedeman  
8/19/82

IE HQ FILE COPY

8208270515 820819  
NMS LIC30  
24-18780-01 PDR

DMB IE-07