

JUN 22 1982

Biomedical Scanning Services  
ATTN: Mr. James Halstead  
9445 Chavez Drive  
St. Louis, MO 63127

License No. 24-18087-01

30-1458

Gentlemen:

This refers to the special safety inspection conducted by Mr. W. P. Reichhold of this office on May 4 and 5, 1982, of activities authorized by NRC Byproduct Material License No. 24-18087-01 and to the telephone discussion concerning our findings with Mrs. Judy Halstead on June 16, 1982.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

In addition to the above areas, the inspector examined actions described in your letter dated February 27, 1981, regarding apparent items of noncompliance found during our January 29, 1981, inspection. We have no further questions regarding these matters.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

J. R. Miller, Chief  
Technical Inspection Branch

Enclosure: Appendix,  
Notice of Violation

cc w/encl:  
DMB/Document Control Desk (RIDS)

RIII

*WR*  
Reichhold/dm  
6/19/82

RIII

*J.P.*  
Wiedeman  
6/22/82

RIII

*J.R.M.*  
Miller  
6/22/82