

AUG 23 1982

Lakeview Hospital
ATTN: Mr. Jerald Race
Assistant Administrator
10010 W. Blue Mound Road
Milwaukee, WI 53226

License No. 48-04585-01

310-3446

Gentlemen:

This refers to the routine safety inspection conducted by Mr. R. E. Burgin of this office on August 17, 1982, of activities authorized by NRC Byproduct Material License No. 48-04585-01 and to the discussion of our findings with you and members of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.


In addition to the above areas, the inspector examined actions described in your letters dated November 6, 1979 and September 4 and 16, 1980, regarding apparent items of noncompliance found during October 1979 inspection and August 1980 investigation. We have no further questions regarding these matters.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.




We will gladly discuss any questions you have concerning this inspection.

Sincerely,



D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1

Enclosure: Appendix,
Notice of Violation

cc w/encl:
DMB/Document Control Desk (RIDS)
RIII  RIII  RIII 
Burgin/jp Sreniawski Wiedeman
8/23/82 8/23/82

IE HQ FILE COPY

8208300325 820823
NMS LIC30
48-04585-01 PDR

DMB IE-07