

Appendix

NOTICE OF VIOLATION

Lakeview Hospital

License No. 48-04585-01

As a result of the safety inspection conducted on August 17, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violations were identified:

1. License Condition 18 states that the licensee shall possess and use licensed material in accordance with statements, representations and procedures listed in application dated March 22, 1979 and referenced letters.

The above application states that quality control checks of your dose calibrator will be made as per Regulatory Guide 10.8, Appendix D, which includes quarterly linearity tests.

Contrary to the above, no linearity tests were performed during the first quarters of 1981 and 1982.

This is a Severity Level V violation (Supplement VI).
This is a repeat item of noncompliance.

2. License Condition 18 states that the licensee shall possess and use licensed material in accordance with statements, representations and procedures listed in application dated March 22, 1979 and referenced letters.


The above application states that your survey meters will be calibrated at least annually.

Contrary to the above, your survey meters were not calibrated between December 1980 and March 1982, a period in excess of the annual calibration requirement.

This is a Severity Level V violation (Supplement VI).
This is a repeat item of noncompliance.

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

8/23/82
Dated


D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1