NRC FORM 591 PART 1 U.S. NUCLEAR REGULATORY COMMISSION (7-91)SAFETY INSPECTION 10 CFR 2.201 Page 1 of 1 2. REGIONAL OFFICE Bridgeport Resco Company, L.A. 6. Howard Avenue Bridgeport, Connecticut adol5 U.S. NUCLEAR REGULATORY COMMISSION 475 ALLENDALE BOAD KING OF PRUSSIA PA 19406-1415 3. DOCKET NUMBER(S) 4. LICENSE NUMBER(S) 5. DATE OF INSPECTION 030-29916 January 26, 1994 LICENSEE The inspect on was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as fellows: Within the scope of this inspection, no violations were observed. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time. During this inspection certain of your activities, as described below or attached, were in violation of NRC requirements. This form is a NOTICE OF MOLATION, which is required to be posted in accordance with 10 U 19.11. was not properly posted to indicate the presence of a . 10 CFR 20.203(b),(c),(d),(e) or 34.42. of sealed so inces were not performed at the proper frequencies. 10 CFR ______ or License Condition Number ____ C. Records of were not properly maintained. or License Condition Number D. Documents were not properly posted or otherwise made available. 10 OFR 19.11. E. Reports or notification of were not made in accordance with 10 CFR _____ or License Condition Number DISIGNA ED GRIGINAL Contied by M.a. Perlie I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC SIGNATURE - LICENSEE PATE SIGNATURE - RC INSPECTOR DATE 9402140001 940126

NRC FORM 591 Part 1 (7-91)

PDR ADDCK 03029916

TOWN OF MAL TO