

AUG 24 1982

Jagmeet Soin, M.D.
811 E. Wisconsin Avenue
Suite 432
Milwaukee, WI 53202

License No. 48-20296-01

Dear Dr. Soin,

This refers to the routine safety inspection conducted by Mr. R. E. Burgin of this office on August 19, 1982, of activities authorized by NRC Byproduct Material License No. 48-20296-01 and to the discussion of our findings with you and Charles Wilson, Ph.D. at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.


Sincerely,



D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1

Enclosure: Appendix,
Notice of Violation

cc w/encl:
DMB/Document Control Desk (RIDS)

RIII

Burgin/jp
8/23/82

RIII

Sreniowski

RIII

Wiedeman
8/24/82

IE HQ FILE COPY

8208310163 820824
NMS LIC30
48-20296-01 PDR

DMB IE-07