

AUG 25 1982

Liberty Hospital
ATTN: Mr. John Massey
Administrator
2525 Glenn West Hendren Drive
Liberty, MO 64068

License No. 24-16178-01

34-10532

Gentlemen:

This refers to the routine safety inspection conducted by Mr. J. R. Madera of this office on August 9, 1982, of activities authorized by NRC Byproduct Material License No. 24-16178-01 and to the discussion of our findings with Mr. Joe Crossett and Mr. Steven Smith at the conclusion of the inspection and the telephone conversation between Mr. Joe Crossett and Mr. J. R. Madera on August 18, 1982.


The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1

Enclosure: Appendix,
Notice of Violation

cc w/encl:
Mr. Joe Crossett, Administrative
Assistant
Mr. Steven Smith, Chief NMT.
DMB/Document Control Desk (RIDS)

R111

R111


Madera/jjm
8/23/82


Wiedeman
8/24/82

IE HQ FILE COPY

8208310362 820825
NMS LIC30
24-16178-01 PDR

DMB IE-07