NRC FORM 591 Part 1 (7-91)

(7-91) 10 CFR 2.201

## SAFETY INSPECTION

		Pag	ge 1 of _/	
1. LICENSEE Eastern Associated Coal Corr Kopperston Mine General Delivery Kopperston, West Virginia 24		2 REGIONAL OFFICE  REGION II  U S NUCLEAR REGULATORY COMMISSION 101 MARIETTA STREET NW SUITE 2900 ATLANTA GA 30323		
3. DOCKET NUMBER(S)	4. LICENSE NUMBER	5. DATE OF INSPECTION		
030-32728	47-25196-01			
		1/11/99		
Regulatory Commission (NRC) rules and reg procedures and representative records, intenfellows:  1. Within the scope of this inspection	julations and the condition views with personnel, and , no violations were observ	your license as they relate to radiation safety and to compliance is of your license. The inspection consisted of selective examina observations by the inspector. The findings as a result of this in ved.  ct the violations identified during the last inspection. We have no	ations of espection are as	
NOTICE OF VIOLATION, which is not also as a second	our activities, as described equired to be posted in ac	was not properly posted	to	
indicate the presence of a _		. 10 CFR 20.203(b), (c), (c)	1),(e) or 34.42.	
B	B of sealed sources were not			
performed at the proper fred	quencies. 10 CFR	or License Condition Number		
C. Records of	Records of were not properly maintained.			
10 CFR or License Condition Number				
D. Documents were not properly	y posted or otherwise man	de available. 10 CFR 19,11.		
E. Reports or notification of		were not made in accord	dance with	
10 CFR or License Condition Number				
		Inspector will be taken to correct the violations identified in the in the requirements of 10 CFR 2.201. No further response will be		
SIGNATURE - LICENSEE	DATE	SIGNATURE - NRC INSPECTOR DATE	3	
9402160066 940111 PDR ADOCK 0303272 C PDR	В	A-7 (A) - 1 margar 11	11/940	