NRC FORM 591 PART 1

U.S. NUCLEAR REGULATORY COMMISSION

10 CFA 2.201	SAFETY	INSPECTI	ON		
				Page 1 of	
1. LICENSEE Community Blood Center, 1 4406 W. Spancer St., Appleto			FICE REGION III U S NUCLEAR REGULATORY COMMI 799 ROOSEVELT ROAD GLEN ELLYN IL 60137	ISSION	
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S		5. DATE OF INSPECTION		
030-32845	48-26428-01		January 26, 1994		
LICENSEE: The inspection was an examination of the act Regulatory Commission (NRC) rules and regulatory and representative records, intervitellows:	lations and the condition	s of your license.	The inspection consisted of selective e	examinations of	
Within the scope of this inspection,	no violations were observ	/ed.			
guestions on those actions at this til	me.		were in violation of NRC registers into		
NOTICE OF VIOLATION, which is re	quired to be posted in ac	cordance with 10 (FR 19.11.		
A			was not properly	posted to	
indicate the presence of a			10 CFR 20.203	(b),(c),(d),(e) or 34.42.	
B	of sealed sources were not				
performed at the proper frequencies. 10 CFR or License Condition Number					
Louised					
10 CFR or License Condition Number					
D. Documents were not properly	posted or otherwise mai	de avallable 10 Ci	H 19.11.		
E. Reports or notification of			were not made i	n accordance with	
10 CFR or License Condition Number				201	
PUBLIC Y				/	
I hereby state that, within 30 days, the actions above. This statement of corrective actions is unless required by the NRC.					
SIGNATURE - LICENSEE	DATE	SIGNATURE - N	RC INSPECTOR	DATE	
9402160076 940126 PDR ADOCK 03032845 C PDR		Donald.	R. Suldion	1-22-94	