

JAN 19 1994

Docket No. 030-14353

License No. 29-18018-01

Testwell Craig Testing Labs., Inc.
ATTN: Michael W. Cannan
President
5439 Harding Highway
Mays Landing, New Jersey 08330

Dear Mr. Cannan:

SUBJECT: SPECIAL INSPECTION NO. 030-14353/93-001

On November 3 and December 21, 1993, Mr. Richard Gibson, Jr. of this office conducted a special safety inspection at the above address and at a field site at 1201 New Fordmill Road, Morrisville, Pennsylvania of activities authorized by the above listed NRC license. The inspection was an examination of your licensed activities as they relate to radiation safety and to compliance with the Commission's regulations and the license conditions. The inspection consisted of observations by the inspector, interviews with personnel, and a selective examination of representative records. In addition, during our inspection we examined the activities covered in your correspondence dated October 1, 1991.

The findings of the inspection were discussed with you and Eugene Samuelson at the conclusion of the inspection.

Based on the results of this inspection, it appears that your activities were not conducted in full compliance with NRC requirements. A Notice of Violation is enclosed as Appendix A and categorizes each violation by severity level in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (Enforcement Policy). You are required to respond to this letter and in preparing your response, you should follow the instructions in Appendix A.

Item A, described in the attached Notice of Violation involving the storage and control of licensed material is classified as a Severity Level IV violation. As indicated in Supplement IV of the NRC Enforcement Policy, significant violations of this type are normally classified as Severity Level III. However, after careful consideration of the factors involved in this specific instance, it is felt this incident posed a minimal health and safety problem. We have exercised our judgment under the NRC Enforcement Policy and have classified this violation as Severity Level IV. Similar violations of this type in the future may result in additional enforcement action.

160012

9402170020 940117
PDR ADOCK 03014353
C PDR

OFFICIAL RECORD COPY - S:\PENDING\TESTWELL.NOV - 01/19/94

RETURN ORIGINAL TO
REGIONS

11:07

Please use the enclosed self-addressed green envelope when you submit your copy to the Regional Administrator, Region I. This will assist us in the timely processing of your response. In accordance with Section 2.790 of NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and your reply will be placed in the Public Document Room. The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Your cooperation with us is appreciated.

Sincerely,

Original Signed By:
Thomas K. Thompson




Walter J. Pasciak, Chief
Industrial Applications Section
Division of Radiation Safety
and Safeguards

Enclosure:
Appendix A, Notice of Violation

cc:
Public Document Room (PDR)
Nuclear Safety Information Center (NSIC)
Commonwealth of Pennsylvania
State of New Jersey

bcc:
Region I Docket Room (w/concurrences)
D. J. Holody, RI

DRSS:PI
Gibson/cmm
1/19/94


DRSS:RI
Pasciak
1/19/94