

July 20, 1982

James G. Keppler Regional Administrator Directorate of Regulatory Operations, Region I!I U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Dear Sir:

Reportable Occurrence Report #82-049/03L-0 Docket #050-373 is being submitted to your office in accordance with LaSalle County Nuclear Power Station Technical Specification 6.6.B.2.(c), observed inadequacies in the implementation of administrative or procedureal controls which threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems.

LaSalle County Station

RHH/GW/djp

Enclosure

cc: Director of Inspection & Enforcement Director of Management Information & Program Control U. S. NRC Document Management Branch Inpo-Records Center File/NRC

FJUL 2 6 1982 PE 82