



UNITED STATES
NUCLEAR REGULATORY COMMISSION



WASHINGTON, D. C. 20555

July 20, 1982

50-213/245/336
Haddam Neck/Millstone

MEMORANDUM FOR: Chief, Document Management Branch, TIDC
FROM: Director, Division of Rules and Records, ADM
SUBJECT: REVIEW OF UTILITY EMERGENCY PLAN DOCUMENTATION

The Division of Rules and Records has reviewed the attached document and has determined that it may now be made publicly available.


J. M. Felton, Director
Division of Rules and Records
Office of Administration 

Attachment: As stated

8208030013 820720
PDR ADOCK 05000213
F PDR

NORTHEAST UTILITIES



THE CONNECTICUT LIGHT AND POWER COMPANY
THE HARTFORD ELECTRIC LIGHT COMPANY
WESTERN MASSACHUSETTS ELECTRIC COMPANY
NORFOLK WATER POWER COMPANY
NORTHEAST UTILITIES SERVICE COMPANY
NORTHEAST NUCLEAR ENERGY COMPANY

General Offices • Selden Street, Berlin, Connecticut

P.O. BOX 270
HARTFORD, CONNECTICUT 06101
(203) 666-6911

July 1, 1982

Docket Nos. 50-213
50-245
50-336
B10529

Mr. Darrell G. Eisenhut, Director
Division of Licensing
Office of Nuclear Regulatory Commission
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Gentlemen:

HADDAM NECK PLANT
MILLSTONE NUCLEAR POWER STATION, UNIT NOS. 1 AND 2
EMERGENCY PLAN PROCEDURES

Due to revisions to previously submitted Emergency Plan Implementing Procedures (EPIPs) related to the Millstone Nuclear Power Station Emergency Plan and pursuant to Section V of Appendix E to 10CFR50, Northeast Nuclear Energy Company (NNECO) hereby submits ten (10) copies of the following procedures:

- (1) EPIP 4102, Revision 6, "Alert"
- (2) EPIP 4103, Revision 6, "Site Area Emergency"
- (3) EPIP 4104, Revision 6, "General Emergency"
- (4) EPIP 4203, Revision 2, "EMT #1 - In Plant Radiological Sampling and Monitoring"
- (5) EPIP 4204, Revision 3, "EMT #2 - Protective Actions for Onsite Personnel"
- (6) EPIP 4211, Revision 2, "On Call Procedure"
- (7) EPIP 4218, Revision 0, "Use of Potassium Iodide (KI) Tablets as a Thyroid Blocking Agent"
- (8) EPIP 4304, Revision 4, "Emergency Response Center and Facilities"
- (9) EPIP 4501, Revision 1, "Radioactive Materials Transport Accident"
- (10) EPIP 4502, Revision 1, "Toxic Material Release"
- (11) EPIP 4601, Revision 1, "Page/Siren System Evacuation Alarm Tests"
- (12) EPIP 4602, Revision 3, "Communications Telephone Test"
- (13) EPIP Form 4102-4, Revision 2, "Alert Emergency: Director of Station Emergency Operations"
- (14) EPIP Form 4103-4, Revision 2, "Site Area Emergency: Director of Station Emergency Operations"
- (15) EPIP Form 4104-4, Revision 2, "General Emergency: Director of Station Emergency Operations"
- (16) EPIP 4214, Revision 0, "Unit 1 Reactor Coolant Post Accident Sampling"

X005
1/10 am
shelf
in back

~~XXXXXXXXXX~~


- (17) EPIP 4215, Revision 0, "Unit 1 Containment Air Post Accident Sampling"
- (18) EPIP 4216, 0, "Unit 1 Reactor Coolant Post Accident Sampling"
- (19) EPIP 4217, Revision 0, "Unit 2 Containment Air Post Accident Sampling"
- (20) EPIP Form 4214-1, Revision 0, "Millstone Post Accident Sampling Data Sheet"
- (21) EPIP Form 4214-2, Revision 0, "Post Accident Sampling - Reactor Coolant Isotopic Worksheet"
- (22) EPIP Form 4214-3, Revision 0, "Post Accident Sampling - Reactor Coolant Chemical Analysis"
- (23) EPIP Form 4214-4, Revision 0, "Determination of Total Dissolved Gas"
- (24) EPIP Form 4214-5, Revision 0, "Post Accident Sampling - Calculation of Gas Sample Volume"
- (25) EPIP Form 4214-6, Revision 0, "Post Accident Sample Data Sheet Reactor Coolant Gaseous Activity"
- (26) EPIP Form 4215-1, Revision 0, "Unit #1 Containment Gaseous Activity Post Accident Sample Data Sheet"
- (27) EPIP Form 4217-1, Revision 0, "Unit #2 Containment Gaseous Activity Post Accident Sample Data Sheet"
- (28) EPIP 4503, Revision 2, "Hazardous Waste and Toxic Substance Spill Incident"
- (29) EPIP Form 4102-1, Revision 3, "Alert Emergency: Shift Supervisor/ Manager of Control Room OPS"
- (30) EPIP Form 4103-1, Revision 2 "Site Area Emergency: Shift Supervisor/ Manager of Control Room OPS"
- (31) EPIP Form 4104-1, Revision 3, "General Emergency: Shift Supervisor/ Manager of Control Room OPS"
- (32) EPIP Form 4201-1, Revision 1, "Worksheet #1 Noble Gas Release Rate"
- (33) EPIP Form 4603-1, Revision 1, "Emergency Operations Facility Radiological Kits"
- (34) EPIP Form 4603-2, Revision 2, "Emergency Operations Facility Access Road - Inventory List"
- (35) EPIP Form 4603-3, Revision 2, "Unit Control Rooms Emergency Equipment"
- (36) EPIP Form 4603-5, Revision 2, "CPF Assemble Area - Radiological Kit"
- (37) EPIP Form 4603-8, Revision 1, "Emergency Equipment Inventory List"
- (38) OP 501, Change No. 1 to Revision 2, "Incident Assessment and Classification-Unit 1"
- (39) EPIP 4305B, Revision 0, "EOF TSO Computer Terminal Operation"
- (40) EPIP 4307, Revision 0, "Unit 1/Unit 2 Control Room Closed Circuit Television (CCTV) System Operation"
- (41) EPIP 4603, Revision 1, "Emergency Radiological Equipment Maintenance and Inspection"

Additionally, ten (10) copies of the Corporate Organization for Nuclear Incidents (CONI) Procedure Manual are hereby submitted by Connecticut Yankee Atomic Power Company (CYAPCO) and NNECO on behalf of the Haddam Neck Plant and the Millstone Nuclear Power Station, respectively.

Should you have any questions, please feel free to contact us.

Very truly yours,

CONNECTICUT YANKEE ATOMIC POWER COMPANY
NORTHEAST NUCLEAR ENERGY COMPANY



W. G. Council
Senior Vice President

cc: Mr. Ronald C. Haynes (3 copies)
Mr. Brian K. Grimes (w/o)
Mr. Falk Kantor (w/o)