

APPENDIX A

NOTICE OF VIOLATION

Florida Power & Light  
Turkey Point 3 and 4

Docket Nos. 50-250 & 50-251  
License Nos. DPR-31 & DPR-41

As a result of the inspection conducted on April 26 - May 25, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

Technical Specification 6.8.1 requires, in part, that written procedures be implemented for safety related equipment.

Contrary to the above, written procedures were not implemented, in that:

1. On May 4, 1982, procedure 2500.1, "Heat Tracing System Normal Operation" was not followed in that the heat tracing annunciator card was unplugged from its receptacle in order to silence the alarms associated with the heat tracing system. This action is not authorized or prescribed by applicable plant procedures.
2. On May 12, 1982, the C boric acid storage tank was removed from service and not logged in the equipment-out-of-service book as required by paragraph 8.4.3 of A.P. 103.2, "Responsibilities of Operators on Shift and Maintenance of Operating Logs and Records".
3. On April 29, 1982, the reactor operator failed to request a check of the local indicator on the Unit 3 Refueling Water Storage Tank (RWST) upon receipt of the "RWST Tech Spec Minimum Level" alarm as required by ONOP 0208.9, "Annunciator Panel G-Miscellaneous."

This is a Severity Level IV Violation (Supplement I.).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: \_\_\_\_\_