NRC FORM 591 PART 1 (7-91)

U.S. NUCLEAR REGULATORY COMMISSION

10 CFR 2.201	SAFETY	INSPECTION	
			Page 1 of _/_
1. LICENSEE MIND-PLISSOURI MEDICAL 3400 WEST THOMAN JEFFERSON CITY, MO	BIVO.	799 F	ON III IUCLEAR REGULATORY COMMISSION IOOSEVELT ROAD I ELLYN IL 60137
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S	3)	5. DATE OF INSPECTION
030-30842	24-2597	19-01	DECEMBER 22, 1993
Regulatory Commission (NRC) rules and regulatory commission (NRC) rules and representative records, intervi- follows:	lations and the conditions ews with personnel, and a	s of your license. The in observations by the insp	to radiation safety and to compliance with the Nuclear spection consisted of selective examinations of ector. The findings as a result of this inspection are as
questions on those actions at this tir	you have taken to correct me. Ir activities, as described t	of the violations identified below or attached, were	I during the last inspection. We have no further in violation of NRC requirements. This form is a 3.11.
A.			was not properly posted to
indicate the presence of a			10 CFR 20.203(b),(c),(d),(e) or 34.42.
В.			of sealed sources were not
performed at the proper frequ	uencies. 10 CFR	or Licens	e Condition Number
C. Records of			were not properly maintained.
10 CFR	_ or License Condition N	Number	- 10070
D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.			
E. Reports or notification of			were not made in accordance with
10 CFR			
· · · · · · · · · · · · · · · · · · ·			
	NE TRIBUT		
9402230150 931222 PDR ADDCK 0303084 C PDR			
I hereby state that, within 30 days, the actions above. This statement of corrective actions is unless required by the NRC.	described by me to the made in accordance with	Inspector will be taken to h the requirements of 10	ocorrect the violations identified in the items checked CFR 2.201. No further response will be submitted
SIGNATURE - LICENSEE	DATE	SIGNATURE - NRO IN	SPECTOR DATE
220062		ALAX-	Itax Walant

NRC FORM 591 Part 1 (7-91)