yellow AUG U4 1982 Alabama Power Company ATTN: Mr. R. P. McDonald Vice President-Nuclear Generation P. O. Box 2641 Birmingham, AL 35291 Gentlemen: Subject: Report Nos. \$0-348/82-18 and 50-364/82-17 CORRECTION This refers to the routine safety inspection conducted by Mr. W. H. Bradford of this office on June 16 - July 15, 1982, of activities authorized by NRC Operating License Nos. NPF-2 and NPF-8 for the Farley facility and to the discussion of our findings held with Mr. W. G. Hairston, Plant Manager, at the conclusion of the inspection. Due to an administrative error the approval signature on the inspection report was omitted. A corrected page is enclosed for insertion into the original report transmitted on July 30, 1982. In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure will be placed in the NRC's Public Document Room unless you notify this office, by telephone, within ten days of the date of this letter and submit written application to withhold information contained therein within thirty days of the date of this letter. Such application must be consistent with the requirements of 10 CFR 2.790(b)(1). Should you have any questions concerning this letter, we will be glad to discuss them with you. Sincerely, 151 H. C. Dance, Chief Reactor Project Branch 2 Division of Project and Resident Programs Enclosure: Inspection Report Nos. 50-348/82-18 and 50-364/82-17, page 1 correction cc's (See page 2) 8209020540 820804 PDR ADDCK 05000348 TEOI

cc w/encl:

W. O. Whitt, Executive Vice President

F. L. Clayton, Jr., Senior Vice President

H. O. Thrash, General Manager-Nuclear Generation

O. D. Kingsley, Jr., Manager, Nuclear Engineering and Technical Services

J. W. McGowan, Manager-Safety Audit and Engineering Review

W. G. Ware, Supervisor-Safety Audit

and Engineering Review

W. G. Hairston, III, Plant Manager

bcc w/encl: NRC Resident Inspector Document Management Branch State of Alabama

RII RII
WBradford:drt JRogge
8/4/82 8/4/82

VBrownlee 8/4/82 HCDance 2/4 /82