

Appendix

NOTICE OF VIOLATION

Commercial Metals Company

License No. 34-20148-01

As a result of the inspection conducted on August 20, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violations were identified:

1. License Condition No. 13 requires that sealed sources containing byproduct material be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above, sealed sources containing millicurie amounts of cadmium-109 and americium-241 which are used daily in a Kevex analyzer were not tested for leakage or contamination from March 31, 1981 to March 4, 1982, an interval of more than six months.

This is a Severity Level V violation (Supplement VI).


2. License Condition No. 16 requires a physical inventory to be conducted every six months to account for all sealed sources received and possessed under the license; records of the inventories shall be maintained for inspection by the Commission.

Contrary to the above, as of August 20, 1982, no physical inventory has been conducted as yet to account for all sealed sources received and possessed under this license.

This is a Severity Level V violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

8-27-82  
Dated

  
D. J. Sreniawski, Chief  
Materials Radiation Protection  
Section 2