

TEXAS UTILITIES GENERATING COMPANY


2001 BRYAN TOWER - DALLAS, TEXAS 75201

R. J. GARY

EXECUTIVE VICE PRESIDENT
AND GENERAL MANAGER

August 24, 1982

TXX - 3561



Mr. G. L. Madsen, Chief
Reactor Project Branch 1
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Tx 76012

Docket Nos. 50-445
50-446

Comanche Peak Steam Electric Station
Steam Generator Compartment Wall
File No: 10110

Dear Mr. Madsen:

On July 1, 1982, we verbally informed your Mr. R. G. Taylor of a deficiency regarding the exterior wall of a steam generator compartment wall.

Our letter TXX-3549 dated July 23, 1982 transmitted our conclusion that this deficiency was not reportable under 10CFR50.55(e). This letter however, incorrectly identified the concrete void as being located in Unit #2 when in fact it is in Unit #1.

Should you have any questions, please advise.

Very truly yours,

R. J. Gary
R. J. Gary

RJG:11

cc: NRC REGION IV - (0 + 1 copy)

Director, Inspection and Enforcement - (15 copies)
c/o Distribution Services Branch, DDC, ADM.
U.S. Nuclear Regulatory Commission
Washington, DC 20555

IE 27