

SUBJECT				S.P. NO.
HEALTH AND SAFETY - NUCLEAR PROGRAM				CR-15
				PAGE NO.
				DATE EFFECTIVE
				April 30, 1958
SUPERSEDES	S.P. NO.	PAGE	DATED	DATE ISSUED
	CR-15	6 para. E,2.	Jan. 22, 1958	April 30, 1958

Paragraph E.2. on page 6 is replaced by the following:

E. 2. Laundering of clothing


- a. All clothing from the controlled area will be monitored before it is sent out of the controlled area to be laundered.
- b. Clothing with an alpha activity less than 1500 disintegrations per minute per seventy five (75) square centimeters will be sent to the Ohio Overall Cleaning Company, 8000 Central Avenue, Cleveland, Ohio for laundering.
- c. Clothing with an alpha activity greater than 1500 disintegrations per minute per seventy five (75) square centimeters will be sent to Nuclear Laundry Service, Inc. P.O. Box 4145, Waterbury 14, Connecticut.

Prepared by

*E. A. Gentry*  
E. A. Gentry  
Personnel Manager

Approved by

*E. J. Gilmore*  
E. J. Gilmore, Manager  
Central Services



Approved by

*A. D. Schwoppe*  
A. D. Schwoppe, Manager  
Materials Division

Issued April 30, 1958 to be effective as of April 30, 1958

*R. L. Shearer*  
R. L. Shearer  
Assistant to the President