Appendix

NOTICE OF VIOLATION

Commonwealth Edison Company

Docket No. 50-304

As a result of the inspection conducted on May 15 through July 16, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

Technical Specification 3.15.1 states: "The unit reactor shall not be made critical unless all the following minimum requirements are satisified." Paragraph 3.15.1B states: "The unit diesel generators (1A and 1B for Unit 1 - 2A and 2B for Unit 2) and the common diesel generator (0) shall be operable."

Contrary to the above, Unit 2 was made critical on June 28, 1982, with the "O" emergency diesel generator out of service. This restart of Unit 2 followed a 78 hour outage during which the reactor was taken to cold shutdown (Mode 5).

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

'AUG 1 3 1982

Dated

R. L. Spessard, Director Division of Project and Resident Programs