

RECEIVED  
NRC

## Washington Public Power Supply System

Box 1223 Elma, Washington 98541 (206) 482-4428

1982 AUG 25 AM 11: 21

Docket No. 50-508

August 20, 1982  
G03-82-831

REGION V FILE

U. S. Nuclear Regulatory Commission, Region V  
Office of Inspection and Enforcement  
1450 Maria Lane, Suite 260  
Walnut Creek, California 94596-5368

Attention: Mr. D. M. Sternberg  
Chief, Reactor Projects Branch No. 1

Subject: POTENTIAL 10CFR50.55(e) DEFICIENCY  
RT INDICATIONS, SAFETY INJECTION TANKS  
AND REACTOR PUMP SUPPORTS (D/N #23)

References: a) Letter G03-82-675, dated July 1, 1982, R. S. Leddick  
to T. W. Bishop, same subject.  
b) Letter G03-82-564, dated June 4, 1982, R. S. Leddick  
to T. W. Bishop, same subject.

Reference a) reported that additional information, required to supplement the final report for the subject condition (Reference b), would be forwarded to your office by August 15, 1982. Specifically, Reference b) would be expanded to fully address the disposition and corrective actions for linear indications found in the safe-end welds of Safety Injection Tanks Nos. 3 and 4.

Ebasco, in conjunction with Combustion Engineering, was directed to assure an evaluation of the safe-end indications was performed per 10CFR50.55(e). Ebasco has received Combustion Engineering's evaluation; however, the CE response is considered unsatisfactory. The Supply System and Ebasco are presently conferring with CE in an attempt to resolve all concerns.

It is anticipated that the requested supplementary information will be provided to your office by October 22, 1982. Should you have any questions or desire further information, please contact me directly.



R. S. Leddick (760)  
Program Director, WNP-3

DRC/tt

cc: J. Adams - NESCO  
D. Smithpeter - BPA  
Ebasco - New York  
WNP-3/5 Files - Richland

8209080553 820820  
PDR ADOCK 05000508  
S PDR

1527