MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205 N

NORRIS L. STAMPLEY SENIOR VICE PRESIDENT

September 2, 1982

Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Region II 101 Marietta St., N.W., Suite 3100 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly

SUBJECT: Grand Gulf Nuclear Station Unit 1 Docket No. 50-416 License No. NPF-13 File 0260/L-835.0 Secondary Containment Valve Inoperable Reference: LER 82-037/03 L-0 AECM-82/378

On August 3, 1982, during normal operations, plant service water was lost due to closure of a secondary containment isolation valve which did not properly indicate its status in the control room. On August 4 another PSW isolation valve was manually closed to comply with T.S. 3.6.6.2. This valve also failed to indicate its proper status in the control room. Attached is LER 82-037/03 L-0.

Yours truly, Alaufley

NLS:ac Attachment

cc: Mr. R. B. McGehee (w/o) Mr. T. B. Conner (w/o) Mr. G. B. Taylor (w/o)

> Mr. Richard C. DeYoung, Director (w/a) Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Document Control Desk (w/a) U. S. Nuclear Regulatory Commission Washington, D. C. 20555

TE 22

HC HC

ANT

T

0

D

S

D

0 ..

2 0

577

8209080598 820902 PDR ADOCK 05000416 PDR

Member Middle South Utilities System