

James W Cook
Vice President - Projects, Engineering
and Construction

General Offices: 1945 West Parnall Road, Jackson, MI 49201 • (517) 788-0453

June 11, 1982

Mr J G Keppler, Regional Administrator US Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

MIDLAND PROJECT -INSPECTION REPORT NO 50-329/82-06 & 50-330/82-06, ITEM 2 FILE: 0.4.2 SERIAL: 17513

References: (1) NRC Letter, C E Norelius to J W Cook, dated April 26, 1982, transmitting Inspection Report 82-06

(2) CPCo Letter, J W Cook to J G Keppler, dated May 28, 1982, Serial 16182, responding to Inspection Report 82-06

Reference (1) deals with misinstalled cables and incomplete cable reel numbers. A meeting was held in Glen Ellyn on May 14, 1982, at which time Consumers Power presented a drait report on misinstalled cables. This letter, as promised by Reference (2), provides the released report on misinstalled cables. The released report has been updated to address the comments generated during the May 14 meeting. The report also provides the dates for which the corrective actions will be completed in order to put the plant in full compliance. A special training session (QCT-1616) was conducted for Bechtel Quality Control on PQCI E-4.0, "Cable Pulling," on March 15, 1982. This training emphasized Activity 2.5 of the PQCI which concerns itself with cable vias, especially in regard to the type of problems identified during the Special Overinspection of cable routing. This training along with the continued emphasis in the training and certification of new electrical QC engineers provides the process corrective action to help assure better performance in this area.

With regard to cable reel numbering, the following actions have been taken to correct the specific instances and to preclude recurrence:

- 1. The cable reel numbers have been corrected, as necessary.
- 2. A cable reel list, with a cross-reference between the old numbers recorded and the real numbers that incorporate the purchase order number and the manufacturer's reel number, has been made a part of the E-4.0 "Cable Installation" record files in the GC vault.

 The number being recorded on inspection records at this time does incorporate the purchase order number and the manufacturer's reel number.

NCR MO1-9-2-022 which documents these actions was closed on 5/17/82 and the plant is now in full compliance.

Consumers Power Company

James W. Cook

Sworn and subscribed to before me on this Ith day of June, 1982.

Notary Public, Jackson County, Michigan

My commission expires September 8, 1984

WRB/BWM/lr

CC: RJCook, NRC Resident Inspector, Midland Site (w/enc) RLandsman, NRC Region III (w/enc) RGardner, NRC Region III (w/enc)

Enclosure: "Report on Cable Installation, Midland Plant Units 1 and 2, June 4, 1982"