This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by the staff on this date.

Facility:

Toledo Edison Company

Davis-Besse Nuclear Power Station

Docket No. 50-346 Oak Harbor, OH 43449 Licensee Emergency Classification: Notification of Unusual Event

Site Area Emergency General Emergency Not Applicable

Subject:

RETURN TO OPERATIONS AFTER 171-DAY OUTAGE

The reactor was made critical at 2:05 p.m. EDT, August 29, 1982, after a refueling and maintenance outage which began March 15, 1982. Post refueling physics testing has been completed and the plant is expected to begin producing electricity on September 3, 1982. During the outage 48 new fuel assemblies were placed in the reactor core for Cycle 3. Among modification and maintenance activities completed were:

Repair of High Pressure Injection Stop Check Valves (PNO-III-82-53)

2. Replacement of cracked low pressure turbine blades (PNO-III-82-41)

Modification of the Steam Generator Auxiliary Feedwater Header (PNO-III-82-38)

4. Seismic Support Modification and Repairs (PNO-III-82-69)

The outage activities were delayed by a strike of Construction Craftsmen (PNO-III-82-39)

The licensee plans to issue a news announcement when the plant begins electrical production. Region III (Chicago) does not plan to issue a news release.

The State of Ohio will be notified.

Region III has been kept informed of startup activities by the resident inspector. This information is current as of 9 a.m. (EDT), September 3, 1982.

Phillips/005

Contact: Reyes J. Streeter R. Spessard 384-2540 384-2541 384-2552

E/W /012

INPO /0//

OIA

AEOD

NSAC

DISTRIBUTION:

H. St. 1003 Chairman Palledino

Comm. Gilinsky Comm. Ahearne

Comm. Roberts Comm. Asselstine SECY

ACRS CA

Air Rights 10/4 8209090142 820903 PDR I&E PNO-III-82-085 PDR

MNBB 103

EDO

PA

MPA

ELD

Regions I 130, II 1021, IV 1017, V 1019 Licensee (Corporate Office) 1040

IE34 Rev. 5/28/82

Willste 1009

DOT: Trans Only

NMSS

MAIL:

ADM: DMB

RES