Duquesne Light Company Beaver Valley Power Station

P.O. Box 4 Shippingport, PA 15077-0004

JOHN D. SIEBER Senior Vice President and Chief Nuclear Officer Nuclear Power Division

(412) 393-5255 Fax (412) 643-8069

February 21, 1994

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

Subject: Beaver Valley Power Station, Unit No. 2 Docket No. 50-412, License No. NPF-73 Fourth Refueling Outage Inservice Inspection Report

This letter forwards the Inservice Inspection Ninety-Day report on ASME Class 1, 2, and 3 components examined during the fourth refueling outage at Beaver Valley Unit No. 2. The ASME Boiler and Pressure Vessel Code, Section XI, Article IWA-6230 requires that an inservice inspection report be submitted to the enforcement and regulatory authority having jurisdiction at the plant site within ninety days after completion of an inservice inspection. The recent at Beaver Valley Unit No. 2 ended on inservice inspection term November 24, 1993.

These examinations are part of Interval 1, Period 2 of the Unit No. 2 ISI schedule. The inservice inspections were performed in accordance with Section XI of the ASME Boiler and Pressure Vessel Code, 1983 Edition through Summer 1983 Addenda.

If you have any questions, please contact Steve Sovick at (412) 393-5211.

Sincerely,

D. Sieber

cc: Mr. L. W. Rossbach, Sr. Resident Inspector

> Mr. T. T. Martin, NRC kegion I Administrator Mr. G. E. Edison, Project Manager

9403070140 940221 ADDCK 05000412 PDR

Attachment

