

U. S. NUCLEAR REGULATORY COMMISSION

REGION I

Report No. 50-247/82-07

Docket No. 50-247 License No. DPR-26 Safeguards Group IV

Licensee: Consolidated Edison Company of New York, Inc.

4 Irving Place

New York, New York 10005

Facility Name: Indian Point Nuclear Generating Station, Unit 2

Inspection At: Buchanan, New York

Inspection Conducted: April 26-30, 1982

Date of Last Physical Protection Inspection: July 31, 1981

Type of Inspection: Routine, Unannounced Physical Protection

Inspectors: William Madden
William Madden, Physical Protection Inspector

8-24-82
date

Approved by: Anthony T. Gody
Anthony T. Gody, Chief, Safeguards Section,
Technical Programs Branch

8-24-82
date

Inspection Summary: Routine Unannounced Physical Protection Inspection
April 26-30, 1982 (Report No. 50-247/82-07)

Areas Inspected: Included a Site Orientation; a review of the Security Plan and Implementing Procedures; Security Organization (Management, Personnel, Response); Security Program Audit; Records and Reports; Testing and Maintenance; Locks, Keys, and Combinations, and Access Control-Personnel.

The inspection involved 36 inspector hours onsite by one NRC region-based inspector. The inspection was initiated during regular duty hours; 4 inspector hours were accomplished during offshift periods.

Results: The licensee was found to be in compliance with NRC regulations except for the following violations: (1) Failure to maintain effective, protected area access controls, and (2) Failure to report the breakdown of protected area access controls to the NRC.

8209090223 820824
PDR ADOCK 05000247
Q PDR