

#### UNITED STATES

#### NUCLEAR REGULATORY COMMISSION

REGIONIV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

Docket: 50-382 License: NPF-38

Entergy Operations, Inc.
ATTN: Ross P. Barkhurst, Vice President
Operations, Waterford
P.O. Box B
Killona, Louisiana 70066

SUBJECT: PUBLIC MEETING OF FEBRUARY 3, 1994

This refers to the public meeting conducted at Waterford 3 on February 3, 1994. The purpose of this meeting was to discuss plant activities associated with Refueling Outage 6, which is scheduled to begin on March 4, 1994. This meeting was attended by those personnel listed in Attachment 1.

We found that your presentation provided a comprehensive review of the preparations, scope, and outage risk assessments for Refueling Outage 6. We note that you have planned an ambitious 46-day outage. The specific topics you discussed at this meeting are listed in Attachment 2.

We note that you plan to have a temporary diesel generator available during reactor coolant system reduced inventory conditions. We consider this to be a positive step that should provide a substantial reduction to risk. Another positive step involved your extensive decontamination efforts in the containment building. ke understand that these efforts are being conducted to allow "street clothes" entry into the containment building by the next refueling outage (Refuel 7) to accommodate planned extensive inservice inspection activities. Other efforts planned for this outage that we consider notable include completion of your commitments associated with Generic Letter 89-10 for your motor-operated valves, the performance of eddy current testing of both steam generators, a modification to the safety-related station batteries to remove nonsafety-related loads, and the replacement of the moisture separator tube bundles with noncopper-containing tubes to help assure that steam generator tube integrity is maintain. 1. Another issue discussed during this meeting involved the resolution of your problems with the containment spray system isolation valves. We understand that, during this outage, you intend to modify the containment spray pump timing circuits so that the respective isolation valves open prior to the pumps starting, thus assuring that valve opening failures do not recur.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter will be placed in the NRC's Public Document Foom.

9403080110 940228 PDR ADDCK 05000382 PDR PDR

IF45

Should you have any questions concerning this matter, we will be pleased to discuss them with you.

Sincerely,

A. Bill Beach, Director Division of Reactor Projects

Attachments:

1. Attendance List

2. Licensee Presentation

cc:

Entergy Operations, Inc.

ATTN: Harry W. Keiser, Executive

Vice President & Chief Operating Officer

P.O. Box 31995

Jackson, Mississippi 39286-1995

Entergy Operations, Inc.

ATTN: Jerrold G. Dewease, Vice President

Operations Support

P.O. Box 31995

Jackson, Mississippi 39286

Wise, Carter, Child & Caraway

ATTN: Robert B. McGehee, Esq.

P.O. Box 651

Jackson, Mississippi 39205

Entergy Operations, Inc.

ATTN: D. F. Packer, General

Manager Plant Operations

P.O. Box B

Killona, Louisiana 70066

Entergy Operations, Inc.

ATTN: L. W. Laughlin

Licensing Manager

P.O. Box B

Killona, Louisiana 70066

Chairman Louisiana Public Service Commission One American Place, Suite 1630 Baton Rouge, Louisiana 70825-1697

Entergy Operations, Inc. ATTN: R. F. Burski, Director Nuclear Safety P.O. Box B Killona, Louisiana 70066

Hall Bohlinger, Administrator Radiation Protection Division P.O. Box 82135 Baton Rouge, Louisiana 70884-2135

Parish President St. Charles Parish P.O. Box 302 Hahnville, Louisiana 70057

Mr. William A. Cross Bethesda Licensing Office 3 Metro Center Suite 610 Bethesda, Maryland 20814

Winston & Strawn ATTN: Nicholas S. Reynolds, Esq. 1400 L Street, N.W. Washington, D.C. 20005-3502 bcc to DMB (IE45)

bcc distrib. by RIV: L. J. Callan Section Chief (DRP/D) MIS System RIV File Section Chief (DRP/TSS)

Resident Inspector Lisa Shea, RM/ALF, MS: MNBB 4503 DRSS-FIPS Project Engineer (DRP/D)

RIV:DRP/D	C:DRP/D 0	D:DRP ()
WBJones Wy	TFStetka D	ABBeach
2/28/94	2/28/94	2/28/94

bcc to DMB (IE45)

bcc distrib. by RIV: L. J. Callan Section Chief (DRP/D) MIS System RIV File Section Chief (DRP/TSS)

Resident Inspector Lisa Shea, RM/ALF, MS: MNBB 4503 DRSS-FIPS Project Engineer (DRP/D)

RIV:DRP/D	C:DRP/D 0	D: DRP U
WBJones WY	TFStetka 🗗	ABBeach
2/27/94	2/28/94	2/23/94

#### REFUEL OUTAGE 6

#### NRC/WATERFORD 3 MEETING ATTENDEES


#### ENTERGY OPERATIONS, INC.

R.	Starkey	Manager, Operations and Maintenance
L.	Laughlin	Manager, Licensing
R.	Burski	Director, Nuclear Safety
G.	Davie	Manager, Operational Experience Engineering
R.	Allen	Manager, Security & General Support
R.	Prados	Senior Engineer - Licensing
M.	Ferri	Director, Modules & Construction
R.	LeBlanc	Licensing Supervisor
	O'Hern	Manager, Training
D.	Shipman	Manager, Planning & Scheduling
	Packer	General Manager, Plant Operations
	Barkhurst	Vice President Operations - Waterford 3
	Keiser	Executive Vice President
	Holman	Manager, Safety & Engineering Analysis
	Azzarello	Director, Design Engineering

#### NUCLEAR REGULATORY COMMISSION

	Ford Stetka	Senior Resident Inspector, Waterford 3 Chief, Project Section D, Division of Reactor Projects
L.	Camper	Acting Deputy Director, Division of Radiation Safety and Safeguards
D.	Wigginton	Sr. Project Manager - Waterford 3, Nuclear Reactor Regulation (NRR)
W.	Beckner	Director, Project Directorate IV-1, NRR
	Dixon-Herrity Powers	Resident Inspector - Waterford 3 Chief, Maintenance Section, Division of Reactor Safety





WATERFORD SES - UNITS

# LEADING THE WAY TO EXCELLENCE



NRC/WATERFORD 3 MEETING
REFUEL OUTAGE 6
FEBRUARY 3, 1994

## NRC/WATERFORD 3 MEETING

REFUEL OUTAGE 6

**FEBRUARY 3, 1994** 

#### AGENDA

INTRODUCTION

R.P. BARKHURST

 PREPARATION ACTIVITIES

D.L. SHIPMAN

SCOPE

D.F. PACKER

MAJOR ACTIVITIES D.F. PACKER

 RELOAD DESIGN/ **ANALYSIS** 

R.G. AZZARELLO

 OUTAGE RISK ASSESSMENT D.F. PACKER

 OUTAGE RISK ASSESSMENT PROGRAM

J.B. HOLMAN

INTRODUCTION

## PREPARATION ACTIVITIES

#### PLANNING DATES

FUEL RECEIPT

JANUARY 19 -FEBRUARY 5, 1994

SHUTDOWN

MARCH 4, 1994 (2400 HOURS)

FUEL LOAD

MARCH 17-25, 1994

· STARTUP

APRIL 18, 1994

## PREPARATION **MILESTONES**

 REFUEL 6 PREPARATION TEAM ESTABLISHED

MARCH 19, 1993

MAJOR ACTIVITIES IDENTIFIED MAY 5, 1993

 OUTAGE ORGANIZATION FORMED

JUNE 18, 1993

 OUTAGE FACILITIES PLAN SEPTEMBER 17, 1993 COMPLETE

 DESIGN CHANGE SCOPE FROZEN (20 DC's, FIELD WORK)

OCTOBER 16, 1993

 FINAL MAINTENANCE ACTIONS DETERMINED

**DECEMBER 18, 1993** 

 OUTAGE SCHEDULE FINALIZED DECEMBER 20, 1993 (RISK ASSESSMENT BEGAN)

 OUTAGE CONTRACTS **ESTABLISHED** 

**DECEMBER 29, 1993** 

## PREPARATION MILESTONES (CONTINUED)

 OUTAGE FACILITIES ERECTION/ JANUARY 5, 1994 STAGING

OUTAGE MANUAL ISSUED

FEBRUARY 4, 1994 (ESTIMATED)

 CYCLE 6 FUEL RECEIPT COMPLETE

FEBRUARY 5, 1994 (ESTIMATED)

 OUTAGE PREPARATION COMPLETE

FEBRUARY 15, 1994 (ESTIMATED)

OUTAGE COMMENCEMENT

MARCH 4, 1994 (2400 HOURS) (ESTIMATED)

SCOPE

#### REFUEL 6 SUMMARY SCHEDULE

**OUTAGE DAYS** 

1 3 5 7 9 11 13 15 17 19 21 23 25 27 29 31 33 35 37 39 41 43 45 2 4 6 8 10 12 14 16 18 20 22 24 26 28 30 32 34 36 38 40 42 44 46

OFF GRID

PLANT SHUTDOWN / COOLDOWN

TED - TRAIN 'A'

TED - TRAIN 'B'

**OPEN MAINT HATCH** 

ICI REMOVAL AND REPLACEMENT

REACTOR DISASSEMBLY

FLOODEP RCS

SET REACTOR HEAD

LIFT REACTOR HEAD

REACTOR REASSEMBLY

REDUCED INVENTORY

FUEL SHUFFLE RCS 44°

FUEL SHUFFLE REDUCED INVENTORY

INSTALL NOZZLE DAMS

-11

STEAM GENERATOR EDDY CURRENT R

REMOVE NOZZLE DAMS

MODEA

CLOSE MAINT HATCH

SAFETY BUS OUTAGES

FILL & VENT

EDG 'B'

EDG 'A'

HEATTP/STARTUP

WATERFORD 3

MSR TUBE BUNDLES REPLACEMENT

TURBINE & GENERATOR WORK

ON GRID

CRITICAL PATH

#### SCOPE

- CRITICAL PATH PROJECTS
  - DISASSEMBLY, FUEL SHUFFLE, REASSEMBLY
  - MSR TUBE BUNDLE REPLACEMENT
- NEAR CRITICAL PATH PROJECTS
  - MDR REPLACEMENT
  - TURBINE GENERATOR INSPECTION
  - SAFETY BUS OUTAGE
  - SUPS OUTAGES
  - STEAM GENERATORS INSPECTION AND NOZZLE DAM INSTALLATION
  - SI, CCW, ACCW AND EDG SYSTEM OUTAGES

#### SCOPE (CONTINUED)

- UNIQUE AND FIRST-TIME ACTIVITIES
  - PERFORM REFUELING WITHOUT CONTRACTOR
  - REPLACING MSR TUBE BUNDLES
  - ICI REMOVAL AT 44' RCS LEVEL USING LONG-HANDLED TOOLS
  - TEST CCW HEAT EXCHANGER PERFORMANCE
  - MODIFICATION OF STATION BATTERY A/B
  - MRPC EDDY CURRENT TESTING OF 'EGG CRATE' REGION OF BOTH STEAM GENERATORS
- LESSONS LEARNED FROM REFUEL 5
  - SAFETY BUS OUTAGE WORK TO BE DONE AT RCS REFUELING LEVEL (44')
  - ENHANCED 'PLANT CONDITION' COMMUNICATION TO GENERAL WORKERS
  - EXTENDED POSTING TO INCLUDE PROTECTED AND OPERABLE TRAINS

**MAJOR ACTIVITIES** 

#### MAJOR ACTIVITIES

- REFUELING
  - 1/3 CORE REPLACEMENT
  - REPLACE 42 ICI'S AND RECOVER 2 ICI'S
- MID-LOOP OPERATION
  - DURING REACTOR DISASSEMBLY (ON 7th DAY) - 1 1/2 DAYS
  - DURING REACTOR REASSEMBLY (ON 31st DAY) - 1 1/2 DAYS
  - TEMPORARY ELECTRICAL DIESEL
- CONTAINMENT ENHANCEMENTS
  - AGGRESSIVE DECONTAMINATION

### MAJOR ACTIVITIES (CONTINUED)

- REFUELING INTERVAL SURVEILLANCES/ TESTING
  - EMERGENCY DIESEL GENERATORS
  - INSERVICE INSPECTION PIPE & SUPPORTS
  - SNUBBERS INSPECTION
  - MOTOR OPERATED AND AIR OPERATED VALVE TESTING
  - SECONDARY PIPING EROSION/CORROSION EXAMINATIONS
  - CHECK VALVE TESTING
  - CONTAINMENT ISOLATION VALVES LOCAL LEAK RATE TESTING
- STEAM GENERATORS
  - 100% EDDY CURRENT TESTING OF BOTH SG'S
  - MRPC OF SELECTED TUBES
    - » 6100 IN LOWER REGION FOR CIRCUMFERENTIAL CRACKING
    - » 300 IN UPPER REGION FOR AXIAL CRACKING
  - SLUDGE REMOVAL AND SECONDARY SIDE INSPECTION

#### MAJOR ACTIVITIES (CONTINUED)

- REACTOR COOLANT PUMPS/MOTORS
  - GENERAL PREVENTIVE MAINTENANCE ON ALL 4 MOTORS - 2 MAJOR, 2 MINOR
- CONTAINMENT SPRAY
  - PUMP AND VALVE TIMING
- TURBINE/GENERATOR AND AUXILIARIES
  - LOW PRESSURE TURBINE #2 INSPECTION, INCLUDING ROTOR REMOVAL
  - GOVERNOR AND THROTTLE VALVE
     MAINTENANCE
  - REBABBITTING OF 2 BEARINGS
  - MOISTURE SEPARATOR REHEATER (MSR)
     TUBE BUNDLES REPLACEMENT AND INTERNAL REPAIRS

### MAJOR ACTIVITIES (CONTINUED)

- MAJOR DESIGN CHANGES
  - DC 3096: MSR TUBE BUNDLE REPLACEMENT
  - DC 3364: MAIN FEEDWATER ISOLATION
    VALVE N2 ACCUMULATOR
    UPGRADE
  - DC 3384: EMERGENCY DIESEL GENERATORS
    OVERHEAD RIGGING SYSTEM
    UPGRADE
  - DC 3387: INSTALL VERSA-VENT SYSTEM ON CEDM'S TO REPLACE EXISTING BALL VALVES
  - DC 3402: A/B BATTERY MODIFICATIONS

## RELOAD DESIGN/ ANALYSIS

### RELOAD DESIGN/ ANALYSIS

- CYCLE LENGTH
  - 18 MONTH CYCLE / 483 EFPD
- METHODOLOGY
  - ALL METHODOLOGIES PREVIOUSLY REVIEWED AND APPROVED
- RELOAD SAFETY ANALYSIS
  - CYCLE 7 EVENTS BOUNDED BY REFERENCE CYCLE
  - NO UNREVIEWED SAFETY QUESTIONS

### OUTAGE RISK ASSESSMENT

### OUTAGE RISK ASSESSMENT

- PREOUTAGE RISK ASSESSMENT OF SCHEDULE BY OUTAGE RISK ASSESSMENT TEAM (ORAT)
  - DETAILED COMPONENT/ACTIVITY REVIEW TO ASSESS FIVE SAFETY FUNCTIONS
    - » DECAY HEAT REMOVAL
    - » REACTIVITY CONTROL
    - » INVENTORY CONTROL
    - » CONTAINMENT
    - » ELECTRICAL POWER
- DEVELOPED OUTAGE RISK ASSESSMENT PROGRAM (ORAP)
  - COMPONENT LEVEL ANALYSIS OF SCHEDULE

## OUTAGE RISK ASSESSMENT (CONTINUED)

- CHANGES TO OUTAGE SCHEDULE
  - CONTINUED SERVICE OF ORAT DURING OUTAGE TO ASSESS CHANGES TO SCHEDULE VS. FIVE BASIC SAFETY FUNCTIONS
- PROTECTED TRAINS
  - USE PROTECTED TRAIN CONCEPT TO ENSURE SAFETY FUNCTIONS ARE MET
- ELECTRICAL POWER WHILE AT REDUCED INVENTORY
  - MINIMUM ONE EDG, TWO INDEPENDENT OFF-SITE POWER SOURCES AND ONE TEMPORARY ELECTRICAL DIESEL

## OUTAGE RISK ASSESSMENT PROGRAM

#### OUTAGE RISK ASSESSMENT PROGRAM

- OBJECTIVE
  - MINIMIZE OUTAGE RISK
  - IMPROVE ASSESSMENT CAPABILITIES
  - COMPONENT LEVEL ASSESSMENT
- DEVELOP INTEGRATED ORA MODEL
  - ORAM TIP
  - IPE MODEL (DIAL CAFTA)
  - SCHEDULE ACTIVITIES AND COMPONENTS
- · THREE N. JR DISPLAYS
  - PROCEDURE COMPLIANCE
  - DEFENSE IN DEPTH
  - RISK PROFILE
- MOST USEFUL DURING REFUEL 6 FOR PROTECTED TRAIN COMPLIANCE