

171100

July 16, 1982

Commander
U.S. Army Missile Command
DRSMI-X0
Bldg. 3651
ATTN: Mr. F. Hart
Redstone Arsenal, AL 35809

Gentlemen:

Subject: Report Nos. 01-00126-16/82-01 and 01-00126-17/82-01

This refers to the routine safety inspection conducted by Mr. P. M. Chambless of this office on June 29, 1982, of activities authorized by NRC License Nos. 01-00126-16 and 01-00126-17 for the Redstone Calibration Facility and the Redstone Arsenal Support Activity facility. Our preliminary findings were discussed with you and members of your staff at the conclusion of the inspection.

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

During the inspection, it was found that certain activities under your license appear to violate NRC requirements. These items and references to pertinent requirements are listed in the Notice of Violation enclosed herewith as Appendix A. Elements to be included in your response are delineated in Appendix A.

In accordance with 10 CFR 2.790(a), a copy of this letter will be placed in the NRC's Public Document Room unless you notify this office, by telephone, within ten days of the date of this letter and submit written application to withhold information contained therein within thirty days of the date of this letter. Such application must be consistent with the requirements of 10 CFR 2.790(b)(1).

The responses directed by this letter and the enclosures are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

(Original signed by A. F. Gibson)
A. F. Gibson, Chief
Technical Inspection Branch
Division of Engineering and
Technical Programs

Enclosure:
See Page 2

8209160357 820902
NMS LIC30
01-00126-16 PDR

July 16, 1982


U.S. Army Missile Command

2

Enclosure:
Appendix A, Notice of Violation

bcc w/encl:
Document Management Branch
State of Alabama

RII

for 
PMChambless:ht
7/15/82

RII


JRPotter
7/15/82

RII


AFGibson
7/15/82