FORM NRC-591 (3-77)

U.S. NUCLEAR REGULATORY COMMISSION

Inspection No. 92-01

I I. LICENSEE	THE RESERVE OF THE PARTY OF THE	LICENSEE ACKNOWLE	
Carter - Wallace	Inc.		gulatory Commission
Carter-Wallace, of Half acre Road Cranbury, n. J.		Region I	ction & Enforcement
randway, n. J.	08512	631 Park Avenue	
3. DOCKET NUMBER(S)	4. LICENSE NUMBER	King of Prussia	Pennsylvania 19406
30-10632, 30-05 312, 30-11836	29-16235-0	1, 29-05595-01	Sept. 28, 1982
The inspection was an examination of the Commission's rules and regulations and the sentative records, interviews with personnel,	activities conducted under y	our license as they relate to	radiation safety and to compliance with the
No items of noncompliance or u			
The following items of noncompliance	related to records, signs,	and labels were found:	
			ION AREA. 10 CFR 20.203(b) or 34.4;
B. Rooms or areas were not prop 10 CFR 20.203(c) (1) or 34.4	nerly posted to indicate th	ne presence of a HIGH RA	ADIATION AREA.
C. Rooms or areas were not prop 10 CFR 20.203(d)	perly posted to indicate th	se presence of an AIRBOI	RNE RADIOACTIVITY AREA.
D. Rooms or areas were not prop	perly posted to indicate th	e presence of RADIOAC	TIVE MATERIAL. 10 CFR 20.203(e)
E. Containers were not properly 10 CFR 20.203(f) (1) or (f) (2)	labeled to indicate the ne-	esence of RADIOACTIVE	E MATERIAL.
		a copy of the operating p	rocedures was not properly posted or
G. Form NRC-3 was not properly	posted. 10 CFR 20.206(+19.11(E)	
H. Records of the radiation expos	sure of individuals were no	ot properly maintained. I	0 CFR 20 401(a) or 34 33(b)
I. Records of surveys or disposal:	s were not properly maint	ained, 10 CFR 20 401(b)	or 34 43(d)
 J. Records of receipt, transfer, di 10 CFR 30.51, 40.61 or 70.51 	sposal export or inventor	ry of licensed material wer	re not properly maintained.
K. Records of leak tests were not	maintained as prescribed	in your license, or 10 CFI	24.25(~)
L. Records of inventories were no	t maintained, 10 CFR 34	26	X 34.23(c)
M. Utilization logs were not maint			
N. Records of radiation survey ins		not maintained 10 CFD	
O. Records of teletherapy electrics	al interlock tests were not	mot maintained. 10 CFR	34.24
P Other	a morrock tests were not	maintained as prescribed	in your license.
10070257 820928 5 LIC30 -16235-01 PDR	Laurence	7, Friedly	Pl. E. C. H. P.
The NRC Inspector has explained a	nd I understand the iter thin the next 30 days.	ns of noncompliance lis	sted above. The items of
9/20/82	Pan	900 V.2	Compliance 1
(Date)		(Licensee Representation	Tuto