AUG 2 3 1990

Docket No. 50-454 Docket No. 50-455

Commonwealth Edison Company ATTN: Mr. Cordell Reed Senior Vice President Licensing Department-Suite 300 Opus West III 1400 Opus Place Downers Grove, IL 60515

Gentlemen:

This refers to the sp cial safety team inspection conducted by Messrs. M. J. Kopp, R. A. Westberg and other NRC representatives of this office on July 23 through August 6, 1990, of activities at the Byron Nuclear Generating Stations, Units 1 and 2, authorized by NRC Licenses No. NPF-37 and -66 and to the discussion of our findings with Mr. S. C. Hunsader at the conclusion of the inspection.

The purpose of this inspection was to follow-up on previously identified items relative to Environmental Qualification (EQ) issues, review the implementation of Generic Letter (GL) 85-06 relative to Anticipated Transient Without Scram (ATWS) mitigating systems, and to review the licensee's implementation of commitments pertaining to Regulatory Guide (RG) 1.97.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as described in the enclosed Notice. The inspection showed that actions had been taken to correct the identified violation and to prevent recurrence. Our understanding of your corrective actions is described in Paragraph 4 of the enclosed inspection report. Consequently, no reply to the violation is required and we have no further questions regarding this matter at this time.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

9009040023 900823 PDR ADOCK 05000454 0 PDC

Commonwealth Edison Company

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

2

Original Signed by Mark A. Ring

M. A. Ring, Chief Engineering Branch

Enclosures: 1. Notice of Violation 2. Inspection Reports No. 50-454/90018(DRS); No. 50-455/90017(DRS) cc w/enclosure: M. J. Wallace, Vice President, PWR Operations T. Kovach, Nuclear Licensing Manager R. Pleniewicz, Station Manager DCD/DCB (RIDS) Licensing Fee Management Branch Resident Inspector, RIII Byron, Braidwood, Zion Richard Hubbard D. W. Cassel, Jr., Esq. D. Chavez, DAARE/SAFE P. Shemanski, NRR H. S. Taylor, Quality Assurance Division J. W. McCaffrey, Chief, Public Utilities Division Robert Newmann, Office of Public Counsel, State of Illinois Center

