

FEB 25 1994

800/80B

Docket No. 50-483

Union Electric Company  
ATTN: Mr. Donald F. Schnell  
Senior Vice President - Nuclear  
Post Office Box 149 - Mail Code 400  
St. Louis, MO 63166

Dear Mr. Schnell:

This refers to the routine safety inspection conducted by Mr. B. I. Bartlett, Ms. D. R. Calhoun, Mr. J. F. Ringwald, and Mr. G. F. O'Dwyer of this office from November 21, 1993 through January 22, 1994, of activities at Callaway Plant, Unit 1, authorized by NRC Operating License NPF-30, and to the discussion of our findings with Mr. J. D. Blosser and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection period one violation with four examples of failure to follow procedures was identified; two of the examples were repeat violations. We are concerned that these failures to follow procedures may be indicative of an indifferent attitude with regard to procedural adherence by some plant personnel. While all of the examples were of relatively minor safety significance, they did reflect an attitude towards procedural compliance that could result in more serious safety issues if allowed to continue. You should ensure that corrective actions concerning this violation are sufficiently broad in scope to ensure that plant personnel are sensitive to the importance of procedural adherence. In addition, we are concerned because of the inappropriate questioning attitude exhibited by several shift personnel in the first example and because the repetitiveness of the second example appears to reflect an inappropriate attitude towards locked components.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice. When preparing your response you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to the Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

08-058

9403090001 940225  
PDR ADOCK 05000483  
Q PDR

DE01

FEB 25 1994

Union Electric Company

2

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosures will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

*Original signed by L.R. Greger*

L. Robert Greger, Chief,  
Reactor Projects Branch 3

Enclosures:

1. Notice of Violation
2. Inspection Report  
No. 50-483/93020(DRP)

cc w/enclosure:

G. L. Randolph, Vice President,  
Nuclear Operations  
J. V. Laux, Manager Quality  
Assurance  
S. E. Sampson, Supervising  
Engineer, Site Licensing  
OC/LFDCB  
Resident Inspector, RIII  
Region IV  
Resident Inspector, Wolf Creek  
K. Drey  
C. John Renken, Engineer  
Policy & Federal Dept.  
Gerald Charnoff, Esq.  
R. A. Kucera, Deputy Director,  
Department of Natural Resources  
Chairman, Illinois Commerce  
Commission

bcc: PUBLIC

SEE PREVIOUS CONCURRENCES

RIII	RIII	RIII	RIII
Farber	Pederson	Olteanu	<i>me</i> Greger 2/25/94

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice. When preparing your response you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to the Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosures will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

L. Robert Greger, Chief,  
Reactor Projects Branch 3

Enclosures:

1. Notice of Violation
2. Inspection Report  
No. 50-483/93020(DRP)

cc w/enclosure:

G. L. Randolph, Vice President,  
Nuclear Operations  
J. V. Laux, Manager Quality  
Assurance  
S. E. Sampson, Supervising  
Engineer, Site Licensing  
OC/LFDCB  
Resident Inspector, RIII  
Region IV  
Resident Inspector, Wolf Creek  
K. Drey  
C. John Renken, Engineer  
Policy & Federal Dept.  
Gerald Charnoff, Esq.  
R. A. Kucera, Deputy Director,  
Department of Natural Resources  
Chairman, Illinois Commerce  
Commission

bcc: PUBLIC

RIII	RIII	RIII	RIII
<i>MAK</i> Farber	<i>MAK for</i> Pederson	<i>CCO</i> Olteanu	Greger
<i>2/24/94</i>	<i>2/24/94</i>	<i>2/24/94</i>	