

Appendix

NOTICE OF VIOLATION

Alma College

License No. 21-18972-01

As a result of the inspection conducted on December 7, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violations were identified:

1. License Condition No. 15 requires that licensed material be possessed and used in accordance with the statements, representations, and procedures contained in certain referenced applications and letters.

The referenced application dated June 4, 1980, states in Item 11.b that the Baird Atomic survey meter will be calibrated once each semester.

Contrary to the above, the survey meter was not calibrated each semester. It had been calibrated February 1980 and August 16, 1982.

This is a Severity Level V violation (Supplement VI).

2. License Condition No. 14.B states the records of leak test results shall be kept in units of microcuries.

Contrary to the above, leak test results were not maintained in units of microcuries for 2 sealed sources leak tested on August 16, 1982.

This is a Severity Level V violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance:

(1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

12/23/82  
Dated

D. J. Sreniawski  
D. J. Sreniawski, Chief  
Materials Radiation Protection  
Section 2