30 - 04983 30 - 10896 30 - 14347

## DEC 2 7 1982

Twin City Testing and Engineering Laboratory, Incorporated ATTN: Mr. Donald E. Johnson, P.E. Quality Assurance Engineer Manager, N.D.T. Department 662 Cromwell Avenue St. Paul, MN 55114 License No. 22-01376-02 License No. 22-01376-03 License No. 22-01376-04

## Gentlemen:

This refers to the routine safety inspection conducted by Mr. D. R. Gibbons of this office on December 13 and 15, 1982, of activities authorized by NRC Byproduct Material Licenses No. 22-01376-02, No. 22-01376-03, and No. 22-01376-04 and to the discussion of our findings with you and selected members of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, no items of noncompliance were identified for License No. 22-01376-02 and No. 22-01376-04, however, for License No. 22-01376-03, certain of your activities appeared to be in noncompliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

IE HO FILE COPY

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. G. Wiedeman, Chief

Materials Radiation Protection Section 1

Enclosure: Appendix, Notice of Violation

cc w/encl:

DMB/Document Control Desk (RIDS)

RIII

Gibbons/sv 12/22/82 Wiedeman