

DEC 2 1982

Docket No. 50-409

Dairyland Power Cooperative  
ATTN: Mr. F. W. Linder  
General Manager  
2615 East Avenue - South  
La Crosse, WI 54601

Gentlemen:

This refers to the routine safety inspection conducted by Mr. M. W. Branch of this office on September 1 through October 31, 1982, of activities at La Crosse Boiling Water Reactor authorized by NRC Operating License No. DPR-45 and to the discussion of our findings with Mr. J. Parkyn at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as specified in the enclosed Appendices A and B. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC's Public Document Room. If this report contains any information that you (or your contractors) believe to be exempt from disclosure under 10 CFR 9.5(a)(4), it is necessary that you (a) notify this office by telephone within ten (10) days from the date of this letter of your intention to file a request for withholding; and (b) submit within twenty-five (25) days from the date of this letter a written application to this office to withhold such information. If your receipt of this letter has been delayed such that less than seven (7) days are available for your review, please notify this office promptly so that a new due date may be established. Consistent with Section 2.790(b)(1), any such application must be accompanied by an affidavit executed by the owner of the information which identifies the document or part sought to be withheld, and which contains a full statement of the reasons which are the bases for the claim that the information should be withheld from public disclosure. This section further requires the statement to address with specificity the considerations listed in 10 CFR 2.790(b)(4). The information sought to be withheld shall be incorporated as far as possible into a separate part of the affidavit. If we do not hear from you in this regard within the specified periods noted above, a copy of this letter, the enclosures, and your response to this letter will be placed in the Public Document Room.

Enclosure Contains  
SAFEGUARDS INFORMATION  
Upon Separation This  
Page is Decontrolled

8301040525 821202  
PDR ADOCK 05000409  
G PDR

IEO1  
IEZ

Dairyland Power Cooperative

Some areas examined during this inspection concern a subject matter which is exempt from disclosure according to Section 73.21(c)(2), Part 73, Title 10, Code of Federal Regulations. This information must be handled and protected in accordance with the provisions of 10 CFR 73.21. Consequently, enclosure B to this letter and your response to the noncompliance identified in enclosure B to this letter will not be placed in the Public Document Room. Therefore, your statement of corrective action regarding the noncompliance identified in enclosure B should be submitted as a separate enclosure to your transmittal letter in the manner prescribed.

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerley,

"Original signed by R.L. Spessard"

R. L. Spessard, Director  
Division of Project and  
Resident Programs

Enclosures:

1. Appendix A, Notice of Violation
2. Appendix B, Notice of Violation (UNCLASSIFIED SAFEGUARDS INFORMATION)
3. Inspection Report No. 50-409/82-18(DPRP)

cc w/encls, w/UNCLASSIFIED SAFEGUARDS INFORMATION:  
J. Parkyn, Plant Superintendent

cc w/encls, w/o UNCLASSIFIED SAFEGUARDS INFORMATION:  
DMB/Document Control Desk (RIDS)  
Resident Inspector, RIII  
John J. Duffy, Chief  
Boiler Section  
Stanley York, Chairman  
Public Service Commission

RII  
*[Signature]*  
Reyes/jp  
11/22/82

RIII  
*[Signature]*  
Wirtle  
11/20/82

RII  
*[Signature]*  
Streeter  
11/24/82

RIII  
*[Signature]*  
Spessard

Enclosure Contains  
SAFEGUARDS INFORMATION  
Upon Separation This  
Page is Decontrolled