


Portland General Electric Company Trojan Nuclear Plant P.O. Box 439 Rainier, Oregon 97048

Mr. R. H. Engelken, Director Nuclear Regulatory Commission 1990 North California Blvd. Walnut Creek, California 94596 October 25, 1978 BDW-1025-78



Dear Sir:

In accordance with the Trojan Operating License, Appendix A, US NRC Technical Specifications, attached is Licensee Event Report No. 78-25 which identifies a situation where testing of the hydrogen mixing system was not performed as required by the Technical Specifications.

D. Withers

Plant Superintendent

BDW/RPS:cb

Attachments

c: J. L. Williams

C. Goodwin, Jr.

D. J. Broehl

R. L. Sullivan

S. R. Christensen

Nuclear Operations Board Trojan Operating Committee

Plant Review Board

L. W. Quinn

D. F. Kielblock

C. J. F eming

L. W. Erickson

Shift Supervisors

F. D. Miller DOE/EFSC

Office of Management Information and Program Control

Edison Electric Institute - Patricia Higgins

File 93.24a