

Appendix A

NOTICE OF VIOLATION

Commonwealth Edison Company

Docket No. 50-010

Based on the inspection conducted on August 16-17, 1978, it appears that one of your activities was in noncompliance with NRC requirements as noted below. This item is an infraction.

Technical Specification 6.2.A.7 requires that surveillance and testing requirements be adhered to. The procedure entitled "Unit 1 Temporary Diesel Generator Test" requires, among other things, that lubricating oil pressure be 80 to 105 psi and fuel oil pressure be 40 to 45 psi.

Contrary to this requirement, these acceptance criteria for the Unit 1 Temporary Diesel Generator Test were not met during the period of March 6 through August 7, 1978.

78110/0016

Q