

APPENDIX A

NOTICE OF VIOLATION

Virginia Electric Power & Light Company
North Anna 1 and 2

Docket Nos. 50-338 & 339
License Nos. NPF-4 & NPF-7

As a result of the inspection conducted on September 6 - October 5, 1982 and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

Technical Specification 6.8.1 requires that written procedures shall be established, implemented, and maintained covering the applicable procedures recommended in Appendix A of Regulatory Guide 1.33, revision 2, February 1978.

Contrary to the above, as of September 28, 1982, Operating Procedures 1.3, 2.1, 5.1, 10.2 and 21.1 and Abnormal Procedure 3 were not properly maintained in that numerous copies in the control room Visible File were not the most current revision.

This is a Severity Level V Violation (Supplement I.).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: NOV 2 1982