

RIV
of Kellogg

pg 5
pava

USE

A-62
61
Howard

FEB 2 1973

99980021

Public Service Electric & Gas Company
Attention: Mr. John F. Batz
Vice President
30 Park Place
Newark, New Jersey 07101

Docket No. 50-311

Gentlemen:

This refers to the inspection conducted by Mr. Brown of this office on January 16 and 17, 1973 of activities authorized by AEC License No. GPPR-53 and to the discussions of our findings held by Mr. Brown with Mr. Suchecki at the conclusion of the inspection.

Areas examined during this inspection are described in the Regulatory Operations Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with plant personnel and observations by the Inspector.

Within the scope of this inspection, no violations or safety items were observed.

In accordance with Section 2.773 of the AEC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the AEC's Public Decision File. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you file a written application with 30 days to this office to withhold such information from public disclosure. Any such application must include a full explanation of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that you can support your position administratively in the event you are denied in a court of law. If you do not file such an application in this report to the specified period, the report will be placed in the Public Decision File.

MAR 2 1973

It is our understanding that the vendor will take the following corrective action:

1. The M. W. Kellogg, Specification No. S416 will be revised to conform with the random radiography requirements of ANSI-B31.7, Nuclear Power Piping Code.
2. The responsible M.-W. Kellogg management personnel will sign any shop traveler operations that have been deleted or revised subsequent to their issuance.

We will review these corrective actions during subsequent inspections.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

H. M. Howard, Chief
Facility Construction and
Engineering Support Branch

Enclosure:

RO Inspection Report No. 995-21/74-1

cc: Mr. Schwilje, QA Manager

bcc: RO Chief, Reactor Construction Branch, HQ
RO:HQ (4)
Directorate of Licensing, HQ (4)
DR Central Files
DR
Local DR
RUC
JRH
State of New Jersey