



EDISON DRIVE
AUGUSTA, MAINE 04336
(207) 623-3521

December 24, 1982
MN-82-253

JHG-82-244

United States Nuclear Regulatory Commission
Region I
531 Park Avenue
King of Prussia, Pennsylvania 19406

Reference: (a) License No. DPR-36 (Docket No. 50-309)
(b) MYAPCo Letter to USNRC, dated December 10, 1982,
RO 82-039/01T-0

Subject: Maine Yankee Reportable Occurrence #82-039/01T-1 - Excure Detector
Calibration

Dear Sir:

Please find enclosed Licensee Event Report for Maine Yankee Reportable Occurrence No. 82-039/01T-1. This event does not represent a violation of Technical Specifications, but is reportable under the requirements of Technical Specification 5.9.1.6.I.

We trust this information will be satisfactory. Should additional information be required, please feel free to contact us.

Very truly yours,

MAINE YANKEE ATOMIC POWER COMPANY

A handwritten signature in cursive script that reads 'John Garrity'.

John H. Garrity, Senior Director
Nuclear Engineering & Licensing

JHG:pjp

Enclosure (2 pages)

cc: Mr. Robert A. Clark
Mr. Paul A. Swetland

8301060365 821224
PDR ADOCK 05000309
S PDR

0355L - SEN

IE22