

APPENDIX A

NOTICE OF VIOLATION

Massachusetts Institute of Technology

Docket No. 50-20

Based on the results of an NRC inspection conducted on September 13-15, 1978, it appears that one of your activities was not conducted in full compliance with NRC regulations as indicated below. This item is a deficiency.

10 CFR 71.12(b) requires the person using a package, pursuant to a general license provided by this paragraph, to have a copy of the specific license, certificate of compliance, or other approval authorizing use of the package and, prior to first use of the package, to submit in writing to the Director of Nuclear Material Safety and Safeguards his name and license number, the name and license or certificate number of the person to whom the package approval has been issued, and the package identification number specified in the package approval.

Contrary to the above requirements, on January 30, 1978, without having a copy of the required certificate and without the submission of the required information to the Director of Nuclear Material Safety and Safeguards, a 210 Ci Transport Group III radioactive shipment was made in Container No. CNS 14-195 (DN 71-9094) for which Certificate No. 9094A had been issued to Chem-Nuclear Company. No exemption or other authorization for this use was indicated.

781130 0377