NRC FORM 591 PART 1

U.S. NUCLEAR REGULATORY COMMISSION

(7-91) 10 CFR 2-201	SAFETY	INSPECTION		Page 1 of
1. UCENSEE Azimuth Technologies Six Landmark Square - Stamford, Connecticut		475 ALLEN	EAR REGULATORY COMMIS NDALE ROAD PRUSSIA PA 19406-1415	SSION
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S	5.	DATE OF INSPECTION	
			November 29, 199	
LICENSEE: The inspection was an examination of the act Regulatory Commission (NRC) rules and regulatory procedures and representative records, intervisellows:	lations and the condition	s of your license. The inspec	ction consisted of selective e	xaminations of
1. Within the scope of this inspection,	no violations were observ	ed.		
The inspector also verified the steps questions on those actions at this tire.		t the violations identified dur	ing the last inspection. We	have no further
During this inspection certain of you NOTICE OF VIOLATION, which is re-				. This form is a
Α			was not properly	posted to
indicate the presence of a			10 CFR 20.203(I	b),(c),(d),(e) or 34.42.
B			of sealed sources	were not
performed at the proper frequ	iencies 10 CFR	or License Co	indition Number	
C. Records of			were not proper	rly maintained.
to CFR	or License Condition N	lumber		
D. Documents were not properly	posted or otherwise mad	le available. 10 CFR 19.11.		
E. Reports or notification of			were not made in	n accordance with
10 CFR	or License Condition N	lumber		
F.				
Certified By:			RETURN OBIGINA	
The state of the s			REGIONI	[E:07
I hereby state that, within 30 days, the actions above. This statement of corrective actions is unless required by the NRC.				
SIGNATURE - LICENSEE	DATE	SIGNATURE - NRC INSPE		DATE
9403150367 940105			Jawrone L	15194

PDR ADDCK 03029279 C PDR